

# Oil Field Environmental Incident Summary

**Incident:** 20130920105650

**Date/Time of Notice:** 09/20/2013 10:42

**Responsible Party:** Enerplus

**Well Operator:** ENERPLUS RESOURCES USA CORPORATION

**Well Name:** YELLOWBIRD 6A-1H

**Field Name:** MANDAREE

**Well File #:** 20100

**Date Incident:** 9/17/2013

**Time Incident:**

**Facility ID Number:**

**County:** DUNN

**Twp:** 149

**Rng:** 93

**Sec:** 6

**Qtr:**

**Location Description:** NA

**Submitted By:** David Van der Vieren

**Received By:**

**Contact Person:** Tony Lucero  
US BANK TOWER  
950 17TH ST STE 2200  
DENVER, CO 80202

**General Land Use:** Well/Facility Site

**Affected Medium:** Well/Facility Soil

**Distance Nearest Occupied Building:**

**Distance Nearest Water Well:**

**Type of Incident:** Valve/Piping Connection Leak

**Release Contained in Dike:** Yes - On Constructed Well Site

**Reported to NRC:** No

	<b>Spilled</b>	<b>Units</b>	<b>Recovered</b>	<b>Units</b>	<b>Followup</b>	<b>Units</b>
<b>Oil</b>	0	barrels	0	barrels		
<b>Brine</b>	0	barrels	0	barrels		
<b>Other</b>	35	gallons	35	gallons		

**Description of Other Released Contaminant:**

Produced Water

**Inspected:**

**Written Report Received:**

**Clean Up Concluded:**

**Risk Evaluation:**

NA

**Areal Extent:**

NA

***Potential Environmental Impacts:***

NA- The entire spill was cleaned up with use of a VAC truck on location

***Action Taken or Planned:***

The entire spill was cleaned up with use of a VAC truck on location

***Wastes Disposal Location:*** NA

***Agencies Involved:*** TERO

***Updates***

---

***Date:*** 9/20/2013    ***Status:*** Reviewed - Assigned to Other Agency

***Author:*** Roberts, Kris

***Updated Oil Volume:***

***Updated Salt Water Volume:***

***Updated Other Volume:***

***Updated Other Contaminant***

***Notes:***

Release of produced water was contained on location, according to the report. Location is within MHA Nation. Report forwarded to BIA and MHA Environmental.